

MARITIME SAFETY COMMITTEE 93rd session Agenda item 22 MSC 93/22/Add.1/Corr.1 12 November 2014 Original: ENGLISH

REPORT OF THE MARITIME SAFETY COMMITTEE ON ITS NINETY-THIRD SESSION

Corrigendum

ANNEX 1

RESOLUTION MSC.365(93) (adopted on 22 May 2014)

AMENDMENTS TO THE INTERNATIONAL CONVENTION FOR THE SAFETY OF LIFE AT SEA, 1974, AS AMENDED

ANNEX

AMENDMENTS TO THE INTERNATIONAL CONVENTION FOR THE SAFETY OF LIFE AT SEA, 1974, AS AMENDED

CHAPTER II-2 CONSTRUCTION – PROTECTION, FIRE DETECTION AND FIRE EXTINCTION

Part C Suppression of fire

Regulation 9 - Containment of fire

- 1 The numbering of subparagraphs in paragraph 7.2.4 is amended as follows:
 - .1 the numbers of the first four subparagraphs are replaced with .1.1, .1.2, .1.3 and .1.4, respectively; and
 - .2 the numbers of the second two alternative subparagraphs are replaced with .2.1 and .2.2, respectively.



ANNEX 4

RESOLUTION MSC.368(93) (adopted on 22 May 2014)

AMENDMENTS TO THE INTERNATIONAL LIFE-SAVING APPLIANCE (LSA) CODE

The reference to MSC.88(66) in the second paragraph of the resolution is replaced with reference to MSC.48(66).

ANNEX 10

RESOLUTION MSC.374(93) (adopted on 22 May 2014)

AMENDMENTS TO THE SEAFARERS' TRAINING, CERTIFICATION AND WATCHKEEPING (STCW) CODE

The wording "100 gross tonnage or more" in operative paragraph 2 of the resolution is replaced with "100 gross register tons or more".

ANNEX 13

AMENDMENTS TO THE CODE FOR EXISTING SHIPS CARRYING LIQUEFIED GASES IN BULK (EGC CODE)

Chapter II - Freeboard and stability

- 4 The text of paragraph 2.3.1 is amended to read:
 - ".1 notwithstanding the requirements above, a stability instrument fitted on a ship before 1 January 2016 need not be replaced provided it is capable of verifying compliance with intact and damage stability, to the satisfaction of the Administration; and"

Certificate of Fitness

- 5 The text in chapeau of paragraph 6.2 is amended to read:
 - ".2* where a waiver permitted by paragraph 2.4 of the Code is granted and the approved stability instrument required by paragraph 2.3 of the Code is not fitted, loading shall be made in accordance with one or more of the following approved methods:"